



Como pedir: MS10 - DH7

Exemplo: **MS10-12**

Tabela de Componentes		
Descrição	Qt.	Material
Base	1	Aço P20 2738
Guia	2	Bronze BM 954
Suporte da Haste	1	Aço P20 2738

Código	DH7	D1	G	D	F	E	H	Ha	Hb	Hc	Hd	He
MS10-08	8	4,5	11	20	8	10	22	12,5	5	11	7	10,5
MS10-10	10	5,5	15	25	10	12,5	27	15,5	5	15	8	11,3
MS10-12	12	7	17	25	12	15	32	18	7	16	10	4

  

Código	B	Ba	C	A	Aa	Ab	Ac	NH7	CS
MS10-08	32	20	20	33	30	24	19	3	10
MS10-10	45	30	25	45	40	32	25	4	18
MS10-12	50	35	30	57	51	39	31	6	20